

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013MY BRZ with FA Engine **NUMBER:** 02-136-12R
SUBJECT: Oil Seepage Diagnosis and Repair Procedures **DATE:** 09/26/12
REVISED: 10/02/12

INTRODUCTION

The purpose of this Bulletin is to provide procedures for the diagnosis and repair of oil seepage which may be coming from the timing chain cover, front camshaft cap, camshaft carrier and / or upper oil pan.

There are four areas that should be closely inspected if an oil leak is reported by the customer:

1. The 6mm tapped hole casting boss area in the left-hand camshaft cap
2. The sealing surfaces between the cylinder head and camshaft carrier
3. The sealing surface between the upper oil pan and the engine block
4. The sealing surfaces of the front timing chain cover


Note: Refer to the April 2011 issue of TIPS for more information on Fluid Leak Detection.

If oil seepage is verified coming from the 6mm threaded hole in the left-hand camshaft cap, install the specified bolt and flat washer.

Bolt: Part# 800206180

Washer: Part# 031106000

Tightening Torque: 6.4 +/- 0.5 Nm
(57 +/- 4 inch-pounds)



Continued...


CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.


SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

If oil seepage is verified coming from between the cam carrier and the cylinder head as shown in the photos below, remove the cam carrier. Clean the machined sealing surfaces thoroughly and then re-seal using Liquid Gasket ThreeBond 1280B (Part No. SOA5499100) or equivalent*. As shown in the photos below, the o-rings between the cam carrier and the cylinder head will need to be replaced as they are not re-usable. This would also be a good time to clean the Active Valve Control System (AVCS) filter screens which are contained in the cam carriers and shown in the photos below. **NOTE:** The filter screens are one-time use and must be replaced if they need to be removed. The replacement filter part # is 14451 AA 050.



Cam carrier seepage seen from top left and lower right side of engine





One-time use cam carrier o-rings which must be replaced.



AVCS filter screens must be replaced if removed.

Continued...

If you find oil seepage between the cylinder block and upper oil pan, remove the upper oil pan, clean the machined sealing surfaces thoroughly and then re-seal using Liquid Gasket ThreeBond 1280B (Part No. SOA5499100) or equivalent*. In addition, the o-rings between the upper oil pan and the cylinder block along with those between the upper and lower oil pan will need to be replaced as they are also one-time use items.




These photos show areas of seepage coming from the upper oil pan to engine block sealing surfaces.

Continued...

Front Timing Chain Cover resealing procedures:

NOTE: Only reseal the front chain cover **AFTER** confirming there is no oil seepage coming from the either cam retainer cap (area 1) and / or the cam carrier (area 3) as previously described.



1. If there are no oil droplets found on the engine under-cover or the lower radiator hose, thoroughly clean the chain cover sealing area along with the surrounding cylinder head and crankcase areas. Re-check for oil seepage again at the next service interval.
2. If the front chain cover is leaking and needs to be resealed, follow the repair procedure in the applicable Service Manual. Thoroughly clean and inspect the sealing surfaces then re-seal using Liquid Gasket ThreeBond 1280B (Part No. SOA5499100) or equivalent*.

*See Service Bulletin 01-167-08 for recommended and alternative sealing materials.

COUNTERMEASURES

INSPECTION AREA	COUNTERMEASURE	STARTING VIN#	STARTING ENGINE #
1	Elimination of 6mm Tapped Hole in Boss of Camshaft Cap	D*600112	0802437
2	Additional sealer for Chain Cover	D*601688	0814630
3	Additional Sealer between Cylinder Head and Cam Carrier	D*600979	0808647
4	Additional Sealer between Engine Block and Upper Oil Pan	D*601429	0811545

Continued...

WARRANTY/CLAIM INFORMATION

For vehicles within the Basic New Car Limited Warranty period, refer to the Subaru Warranty Wizard® for claim submission information. Use the chart below for the 6mm bolt installation procedure outlined on pg. 1 of this bulletin.

LABOR DESCRIPTION	LABOR OPERATION #	FAIL CODE	LABOR TIME
LH Cam Cap Boss Oil Seepage Repair	A243-611	AFR-34	0.3

NOTE: Liquid gasket ThreeBond 1280B can be claimed using part number SOA635065, quantity one (1) per repair order. This part number is non-orderable and used for claim purposes only.